2012

WATER DISTRIBUTION ANNUAL REPORT



CITY OF FINDLAY WATER DISTRIBUTION DEPARTMENT

136 N. BLANCHARD ST.

FINDLAY, OHIO 45840

The City of Findlay Water Distribution Department had 13 full time employees at the end of 2012.

Employees are:

Maintenance Supervisor
 Secretary
 Waterline Maintenance Worker III
 Waterline Maintenance Worker II
 Waterline Maintenance Technician

Collectively, the Water Distribution Department totals 197 years of service.

Members of the Water Distribution staff are:

Jeff Betts-Maintenance Supervisor Betty Jones-Administrative Assistant Tim Frysinger- Waterline Maintenance Technician Jeff Kolhoff-Waterline Maintenance Worker III Ken Paul-Waterline Maintenance Worker III Bob Wagner-Waterline Maintenance Worker III Larry Pocock-Waterline Maintenance Worker II Bryan Miller-Waterline Maintenance Worker II Mike Rader-Waterline Maintenance Worker II Jordan Endicott- Waterline Maintenance Worker II Kyle Jordan -Waterline Maintenance Worker II Anthony Orians-Waterline Maintenance Worker II

DEPARTMENT RESPONSIBILITIES

At the end of 2012 the City of Findlay's Water Distribution Department was responsible for 307.25 miles of city water main. There are 19,130 water service connections, meter settings, and 2,383 fire hydrants.

The department also documents all activities handled including major activities such as: installation of water lines, water taps, service line renewals, main break repairs, hydrant repairs, locating of water lines for other utilities and contractors, repairs to streets, driveways, and sidewalks damaged by our activities, inspections of water service line installations, collection of bacteria samples for new water line installations and leak detection, review of all proposed construction plans, to make sure the proposed water lines are in compliance with Ohio EPA rules and regulations and AWWA Standards, and maintenance and minor repairs to the department's vehicles and equipment.

NEW WATER SERVICE CONNECTIONS



From 1989 through 2012, over a twenty four (24) year period, we have added 5,262 new water service connections to our system.

1989	140	2001	293
1990	186	2002	316
1991	187	2003	242
1992	162	2004	275
1993	209	2005	271
1994	272	2006	234
1995	245	2007	145
1996	268	2008	107
1997	285	2009	66
1998	346	2010	79
1999	360	2011	80
2000	403	2012	91

For the year 2012, $71 - \frac{3}{4}$ inch services were installed taking 852 man-hours and 122 backhoe hours, 9 - 1 inch services were installed taking 75 man-hours and 11 backhoe hours, $1 - 1\frac{1}{2}$ inch service was installed taking 12 man-hours and 1 backhoe hours, 3 - 2 inches services were installed taking 121 man-hours and 6 backhoe hours. There was another 7 additional main line taps, 2 - 4 inch, 5 - 6 inch, requiring 53 man-hours and 9.50 backhoe hours.



A total of 44 water services were renewed taking 582.50 man-hours and 108 backhoe hours. There were $36 - \frac{3}{4}$ inch services, 7 - 1 inch, and 1- 4" services renewed.

LINE LOCATING

Combined with the leak-locating program is the line locating program. This program is for locating our water lines for other utilities, contractors, developers and consultants.

We are a member of the Ohio Utilities Protection Service. They send us locates via an OUPS printer and we in turn notify other city departments as needed.

1989	222	2001	5817
1990	784	2002	5960
1991	1217	2003	5146
1992	2072	2004	6079
1993	2446	2005	6506
1994	2112	2006	6748
1995	3162	2007	5897
1996	3528	2008	5713
1997	4070	2009	5162
1998	4410	2010	5225
1999	3829	2011	5956
2000	6725	2012	6182

This figures out to be 24.6 locates per day for the 251 working days in a year. Along with line locating, there is also the collection of bacteria samples for testing of new water main installations. There were 23 bacteria samples collected this year.

METER SHOP REPAIRS AND TESTING

Growth in locates from 1989 to 2012:

Tested	126
Repaired	331
Junked	894
Sent Back	374

FIRE HYDRANT FLUSHING



The Water Dist. Department performs all of the flushing, tagging, and pumping of hydrants in our system. We constructed three truck mounted flushing units that allow us to open the hydrant completely to allow the needed velocity to properly flush the main line. Without these units, water would be flushed clear across the street potentially causing motorists harm, as it was experienced in the past. Also, since we have taken over the hydrant flushing, we have found that we can properly maintain the hydrant while we are there, saving time in return trips therefore saving money.

METER CHANGES

The Water Distribution Department changed a total of 1343 meters in 2012 for use with the new meter reading system. These activities took 415.75 hours of labor and 12.25 hours of vactor to accomplish.

GOALS FOR 2013

Continue maintenance of the new Badger Meter Galaxy meter reading system by changing meters and meter covers.

Finish the painting of hydrants so they all look identical.

Continue to update all waterline maps in house for future reference for GIS and EPA Net 2 for water hydraulics.

Start a valve, locate and exercise program.

Continue the annual large meter test and repair program.

Continue the leak detection survey.

Over see an ongoing corrosion control project being done through the Engineering Department.

I would like to thank the employees of the Water Distribution Staff, who work diligently in providing clean safe drinking water. Along with helping in storm disaster cleanup and snow removal our Water Distribution employees provide an excellent service to our community. Thank you to our Administrative Assistant, Maintenance Workers and locator.

Thank You,

Jeff Betts Water Distribution Supervisor

LIST OF DEPARTMENTAL ACTIVITIES PERFORMED

Cold Mix repairs temporary patch to street 6 different sites	excavations Man-hours	9	Backhoe Hrs	3
66 gate box repairs	Man-hours	169.75	Backhoe Hrs. Vactor Hrs	12.25 30.25
29 gate valves repaired	Man-hours	437.75	Backhoe Hrs. Vactor Hrs	56 5
14 fire hydrants installed or replaced	Man hours	259	Backhoe Hrs.	39
47 fire hydrants repaired	Man-hours	211	Backhoe Hrs. Vactor Hrs	34.50 1
6 fire hydrants checked for damage	Man hours	8.75		
1 customers new water service line installation inspections	Man hours	.50		
86 meter lids replaced	Man hours	47.75		
80 broken mains varying in sizes from 1 inch and up. Includes regular hours, overtime hours and call out				
(11 1	1 6 1	1010 15	D 11 II	1.10
stand-by hours	Man-hours	1019.45	Backhoe Hrs.	143
66 leaks checked out	Man-hours Man-hours	1019.45	Backhoe Hrs. Backhoe Hrs.	143 7
66 leaks checked out	Man-hours	101.25		
66 leaks checked out 9 meters set in	Man-hours Man-hours	101.25 6		
66 leaks checked out9 meters set in21 meter reductions	Man-hours Man-hours Man-hours	101.25 6 17		
 66 leaks checked out 9 meters set in 21 meter reductions 10 meters taken out 	Man-hours Man-hours Man-hours Man-hours	101.25 6 17 12	Backhoe Hrs.	7
 66 leaks checked out 9 meters set in 21 meter reductions 10 meters taken out 1343 meters changed 	Man-hours Man-hours Man-hours Man-hours	101.25 6 17 12 415.75	Backhoe Hrs.	7
 66 leaks checked out 9 meters set in 21 meter reductions 10 meters taken out 1343 meters changed 16 pressure checks 	Man-hours Man-hours Man-hours Man-hours Man-hours	101.25 6 17 12 415.75 12.25	Backhoe Hrs.	7
 66 leaks checked out 9 meters set in 21 meter reductions 10 meters taken out 1343 meters changed 16 pressure checks 3 turn on service 48 turn off for repairs regular hours, 	Man-hours Man-hours Man-hours Man-hours Man-hours Man-hours Man-hours	101.25 6 17 12 415.75 12.25 1.25 28.70	Backhoe Hrs.	7

3 service lines repairs	Man-hours	13.50	Backhoe Hrs.	1.5
10 settings lowered	Man-hours	14		
10 settings moved	Man-hours	101.25	Backhoe Hrs.	12.5
21 settings raised	Man-hours	23.75		
56 settings repaired	Man-hours	105.25	Backhoe Hrs. Vactor Hrs.	13 5
9 no water calls	Man-hours	7.50		
3 nipples installed	Man-hours	1.75		
33 Temporary meter set and removed	Man-hours	51.50		

MISCELLANEOUS JOBS

There were 163 different miscellaneous jobs done by water distribution for a total of 1913.95 labor hours with 215.25 backhoe hours, 1 vactor hours and 7 dump truck: Picked up barricades, stoned holes, locate shut off for plumber, check holes, met with many contractors and customers over water lines, set up arrow boards for Police Department for parades, set fishing docks, dig out holes for Street Department to hot patch, work gate valves for contractors installing new main lines, during the June wind storm 519.50 labor hours, 226 backhoe hours, 11 bobcat hours, 282.50 dump truck hours and many other miscellaneous jobs too numerous to mention.